

- 1.Use plastic head nut and M10 X 100 screw to fix the metal base on the block;
 - 2. Insert the imop battery;
 - 3. Turn on the switch;
 - 4. Use the timer to set up the time;
 - 5. Push the blue button to rotate the body up and down;
 - 6.Lift the location pin and then rotate the body left and right, release the location pin after get the angle you wanted.

